


Suggested wiring to control a two speed pump with an SAS109 Sequencing Air Switch

INT047 7/2003



This is a sales support document.
Tecmark not liable for actual wiring.
Tel. USA-440-205 7600 Fax USA-440-205 7601